

Unit 2 - First Floor Level Core/ Office Plan



Different Wall Types - refer to drawing W038-S-DR-818

General Stud Wall - (with Insulation)





Indicative Above Ground Drainage Positions:-Internal Drainage 'pop-up' locations added as advised on MBA's Drawing: 20-246-M-760



Drainage Stack



Rodding Eye



Drainage Pipework

Rev C5: Additional Dims added as requested. HM. 11.12.2022
Rev C4: Lift/Shaft adjusted. PAL - 02.12.2022
Rev C3: Whitewall Thickness Changed. Internal Drainage 'pop-up' locationsadded as advised on MBA's Drawing: 20-246-M-760.
Drainage stack positions slightly tweaked to a more suitable location / differs from MBA's positioning. Layout to be reviewed with EirEng; Addtional Setting Out Dims' Added to Stair. HM - 29.11.2022
Rev C2: Door Numbers adjusted to suit Door Schedule. HM - 20.09.2022
Rev C1: Construction Issue. HM - 12.08.2022

Drawing Status:
CONSTRUCTION

CMP

Architects Client

Beatty Road, Waltham Cross

First Floor Level Core/ Office Plan

Scale Drawn 1:50@A1 / 1:100@A3 HM Date **01.08.2022** Revision **C5**

Drg.No. W038-U2-DR-151

Do not scale from this drawing, use figured dimensions only. Subject to accurate site survey. All dimensions to be checked and verified for any discrepancies. All drawings to be read in conjunction with all CMP Architects and other consultants' contract documentation. Any discrepancies to be reported before any work commences. All items installed by others are to be fully site coordinated and programmed with the Contractor. All products to be installed to manufacturers recommendations.

©Copyright CMP Architects Ltd