

# HYBRID OFFICE/STUDIO BUILDING







- · Goods loading to the ground floor
- · Air conditioning and heating
- 9 parking spaces
- Excellent road access to M11 and M25
- Highams Park station 1.09 miles
- Neighbours established supermarket chains






## **Description**

The premises comprises a mid terrace two storey hybrid office and studio/warehouse property on a well established business park. The property is arranged to provide mainly clear space on each floor with the ground floor given to functional warehouse/workshop use and the first floor fitted as offices.

#### Location

Trinity Park is located adjacent to the A406 North Circular Road approximately midway between Hall Lane and Crooked Billet Roundabout accessed from the eastbound carriageway. The M11 motorway is located 2 miles east providing immediate access to the M25.



# **Accommodation / Availability**

Unit	Sq ft	Sqm	Rent	Availability
Unit - 2	2,900	269.4	£16 /sq ft	Available

### **Tenure**

New Lease

**EPC** 

D (87)

**VAT** 

Not applicable

# Configuration

Not Fitted

#### **Contacts**

Nowsher Alam 07967776358 nowsher.alam@strettons.co.uk

Jamie Smith 07870 850097 jamie.smith@strettons.co.uk

Charles Wood 07970 434876 charles.wood@strettons.co.uk



#### **Further Information**

View on Website

Strettons and their clients give notice that: 1. They are not authorised to make or give any representations or warranties in relation to the property either here or elsewhere, either on their own behalf or no hehalf of their client or on themalf or the review. They assume no responsibility for any statement that may be made in these particulars. These particulars do not form part of any offer or contract and must not be relied upon as statements or, representations of fact. 2 hay areas, measurements or distances are approximate. The text, photographs and plans are for guidance only and are not necessarily comprehensive. It should not be assumed that the property has all necessary planning, building regulation or other consents and the Agents have not tested any services, equipment or facilities. Purchasers must satisfy themselves by inspection or otherwise. Generated on 25/04/2024